NEX1 Technologies CO., Ltd.

Optical Fiber Patch Cord QC Flow Chart

REVIEWED	PREPARED
	REVIEWED

Production flow		Quality control items		Quality control contents							
Flow chart	Procedures	Equipments	Characteristics		Specifications	Interval	Sampling	Test methods	Recordings	Guideline	Controllers
	Parts/ components distribution		Parts confirmation, specifications, quantity		Customer's order			Visual inspection			Inventory control
	2. Cable cutting	Cutting machine	Length		Standard operation guide, customer's order			Tape measure		Cable cutting	Assembly worker
	3.Parts insertion		Parts items, parts arrangement consequence		Standard operation guide			Visual ins pection		Parts insertion	Assembly worker
	4. Adhesive preparation	Foam separator、 electronic scale	Time, pressure		Standard operation guide			Visual inspection		Adhesive preparation	Assembly worker
	5. Adhesive toasting	Toaster	Temperature, time		Standard operation guide			Visual inspection		Adhesive toasting	Assembly worker
	6. Polishing	Polishing machine	Time, pressure, spinning speed, polishing blade		Standard operation guide					Polishing	Assembly worker
	7. Sectional inspection	Sectional inspection scope	Section outer appearance		Standard operation guide	Total quality control (T.Q.C)	NA	X 400 micro-scope visual inspection	Polishing data recording	Sectional inspection	Assembly worker
)	8. Assembly	Pliers	Outer appearance		Standard operation guide			Visual inspection		Assembly	Assembly worker
$\left \begin{array}{c} \downarrow \\ \Diamond \\ \downarrow \end{array}\right $	9. Optical characteristic test	JDS	Insertion loss, Reflection loss		Standard operation guide	Total quality control (T.Q.C)	NA	Measurements		Test	Assembly worker
	10. Sectional inspection	Sectional inspection scope	Section outer appearance		Standard operation guide	Total quality control (T.Q.C)	NA	X 400 micro-scope visual inspection		Sectional inspection	Assembly worker
	11. Packing		Quantity, labeling, numbering ring		Standard operation guide	Total quality control (T.Q.C)	NA	Visual inspection		Packing	Assembly worker
	12. Final inspection		Outer appearance, quantity		Standard operation guide	Total quality control (T.Q.C)	NA	Visual inspection	Final inspection report		Quality assurance
	13. Shipping										Sales representative
Пен	Production Processing Quantity inspection Quality inspection Yield		Version [Date			Summaries of the	ne revision			Revised by
Flow marks			2.0 9	6.7.2	Updated revised version	1					Andy Tsao